Georgia Environmental Protection Division - Underground Storage Tank (UST) Management Program

Public Record Report for FFY 2022

General Information

Total Number of UST Facilities: 9,822
Total Number of USTs: 29,467

Public Record Posted Date: December 16, 2022

Public Record Posted Date: December 16, 2022

Summary Information For Inspections

Number of UST Facilities Inspected: 3,901
Inspection Period Dates Were From: To: 10/01/2021 - 09/30/2022
Percent Compliance (Combined Measure): 39%

Note: Tank, facility, and on-site inspection information is based on underground storage tanks regulated under Subtitle I that satisfy the definition of UST in 40 CFR 280.12, except for those tanks identified in 40 CFR 280.10(b) as excluded USTs and those deferred in 40 CFR 280.10(c). Inspections measure compliance with EPA TCR for the combined measures of Spill Prevention, Overfill Prevention, Corrosion Protection and Realease Detection.

Summary Information for Releases

Number of Confirmed UST Releases: 188

Release Period Dates Were From: To: 10/01/2021 - 09/30/2022

Summary Information for Release Sources And Causes

| | | | | Cause | | | | | | | | | | | | |
|------------------------------|-----|-----|-------|-------|----------|-----|-----------|-----|-----------|-----|---------|----|-------|----|---------|------|
| Source | | | Spill | | Overfill | | Phys/Mech | | Corrosion | | Install | | Other | | Unknown | |
| | # | % | # | % | # | % | # | % | # | % | # | % | # | % | # | % |
| Tank | 21 | 11% | 1 | 5% | 1 | 5% | 0 | 0% | 1 | 5% | 0 | 0% | 0 | 0% | 45 | 214% |
| Piping | 15 | 8% | 0 | 0% | 0 | 0% | 4 | 27% | 1 | 7% | 1 | 7% | 0 | 0% | 11 | 73% |
| Dispenser | 12 | 6% | 1 | 8% | 0 | 0% | 5 | 42% | 0 | 0% | 0 | 0% | 1 | 8% | 18 | 150% |
| Submerged Turbine Pump | 7 | 4% | 0 | 0% | 0 | 0% | 1 | 14% | 1 | 14% | 0 | 0% | 0 | 0% | 3 | 43% |
| Delivery Problem | 2 | 1% | 3 | 150% | 1 | 50% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% |
| Other | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 2 | 0% |
| Unknown | 131 | 70% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 119 | 91% |
| Totals | 188 | | 5 | | 2 | | 10 | | 3 | | 1 | | 1 | | 198 | |

= number, % = percent of total number

If you have site specific or general UST questions or you cannot download this report, please contact the UST Program by calling 404-362-2687.

Note: Release, source and cause information is based on underground storage tanks regulated under Subtitle I that satisfy the definition of UST in 40 CFR 280.12, except for those USTs indentified in 40 CFR 280.10(b) UST's deferred in 40 CFR 280.10(c) and those used for emergency power generation (deferred from release detection by 40 CFR 280.10(d)) are included as part of the public record.

This report reflects data from releases reported to EPD during the time period of the report. Source and cause data were collected using on-site inspections and reports from facilities. The locations of these releases were notidentifiable. "OTHER" is an identifiable source that does not fit specific locations identified in the chart.